


## Passenger Backrest – Honda VT750 C2 (1997-2003)



General information and comments:

- 1. Do not tighten the screws too tight.
- 2. Tighten all screws at the end after assembling the entire structure on a motorcycle.
- 3. Always check the screw length and pitch compare to the original. The final length of the screw depends on the installed components on the bike.